



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Kathleen Clarke  
Executive Director

Lowell P. Braxton  
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

January 29, 2002

TO: Minerals File

FROM: Tom Munson, Senior Reclamation Specialist *m*

RE: Site Inspection, Company, MCW Enterprises, Gold Queen Mine, S/017/035, Garfield County, Utah

Date of Inspection: October 26, 2001

Time of Inspection: 3:30 p.m.

Conditions: Sunny

Participants: Bobby Hogget, MCW Enterprises; Buzz Rakow, BLM; Tom Munson, DOGM

**Purpose of Inspection:** To inspect site due to operator request for transfer from MCW Enterprises, Inc. to Martinique Mining Corp. To document the amount of disturbance, generate a map and take photos of the site.

**Observations:**

We want to remove the derelict equipment that still remains on site. There are several ponds. There is some grooming, smoothing and recontour work. I GPS'd the site, file number R102520A. Photos were taken of the site. This site is commonly referred to Million Dollar Gulch, which was originally owned by Gil Cotlia, Green River Holdings, then transferred to MCW, and now being transferred to Kim Wilson.

They have agreed to take out the two hoppers that are down below. Mr. Rakow of the BLM told Mr. Hogget that this is what he would like to be done. The two embankments are to be removed, but leave the remainder of vegetation in place. Mr. Rakow said this would then probably satisfy the BLM's stringent requirements.

**Conclusions and Recommendations:**

A lot of the site is revegetating with rabbit brush and what looks like willows being in the bottom of the drainage. We could probably give credit for at least 20-30 percent of the site being reclaimed on it's own. The remainder requires the removal of some pond embankments and some general recontouring and reshaping of the channel.

jb


cc: Buzz Rakow, BLM (UTU-71613)

S17-35-ins.doc



# Gold Queen Mine

## S017/035




 **mine site**

This map was produced on 1/29/2002

Raggy Canyon Quadrangle  
SE1/4 of Section 28  
T31S, R11E

This Product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause misalignment of data layers.







ONLY ONE PHOTO TAKEN LOOKING SW, THE  
OTHER PHOTOS DID NOT COME OUT.